

Portable Generators Range

	kVA 50Hz		kVA 60Hz	
	3 ph	1 ph	3 ph	1 ph
QAS 14	12.5	9.9		
QAS 20	20	14.5		
QAS 30	30	21.7		
QAS 45	45			
QAS 60	60			
QAS 80	80			
QAS 100	100			
QAS 15			15	11.9
QAS 22			22	17.1
QAS 35			35	25.7
QAS 55			55	
QAS 70			70	
QAS 95			95	
QAS 115			115	
QAX 12	12	10.1		
QAX 20	20			
QAX 30	30			
QAX 24			24	
QAX 35			35	
QAS 125	125			
QAS 150	150			
QAS 200	200		231	
QAS 250	250		293	
QAS 325	325		345	
QAC 500	500		450	
QAC 750	750		875	
QAC 1000	1000		1140	



We are committed

www.atlascopco.com